

# SOLUTIONS TO STATIC PROBLEMS

## CLEANROOM HARD TABLET COLLECTION BINS

Hard tablets are very dry and the subsequent and numerous constant collisions of these tablets during collection causes very high static charges with the collection container.

These charges can cause painful operator shocks as well as unwanted contamination attraction. Placing a 3850 Ionstorm or 3024L Bar above the collect bin will resolve both issues.

Occasionally transparent covers are placed over the collection bins to assist in preventing contaminant release or attraction. In this event a 3850 can not be installed but 3810 pairs of single point Ionstorm bars can be installed into the cover plate.

